

EnviroGear Pumps Solves Pump Problems at Cargill Vitamin E Plant

EnviroGear[®] Pump Solves Pump Problems at Cargill Vitamin E Plant

Challenge

- Pumping a sterol mixture with a mechanically sealed gear pump
- Seal leakage causing high maintenance costs
- Seal leakage causing environmental, health and food safety problems
- Unplanned maintenance incidents resulting in process downtime
- Switching pump brands typically requires significant process piping, pump mounting and drive changes

Solution

 Replace existing pump with an EnviroGear seal-less gear pump model S1-32-SS that was dimensionally interchangeable with the existing mechanically sealed gear pump

Results

- Maintenance-free pump service for 6 months to-date
- Seal-less design eliminated maintenance costs associated with seal leakage
- Seal-less design eliminated environmental, health and food safety concerns
- No downtime, no process disruptions due to the pump performance

"EnviroGear Pump understands the failure modes of the competition and has done their part to engineer a better, more reliable and cost effective product. Their service to the customer has also been exceptional."

- Mark Hughes, Maintenance Manager, Cargill Vitamin E



PSG 22069 Van Buren Street Grand Terrace, CA 92313-5607 USA P: +1 (909) 422-1731 F: +1 (909) 783-3440 envirogearpump.com

