

Unilever Installs EnviroGear Seal-less Pump to Solve Soapy Problem

Challenge

- Soap production required 24 / 7 / 365
- Unplanned maintenance incidents resulting in downtime
- Dynamic shaft leakage causing environmental, health and safety problems
- Significant lost product costs

Solution

 Replace existing pump with an EnviroGear Model S1-55-CS Seal-less Gear Pump

Results

- Maintenance-free pump service for 10 months
- No downtime or process disruptions due to the pump performance
- Environmental, safety and health concerns were eliminated

"It is a difficult environment here that requires a heavy-duty machine, not a delicate one. We feel that we have a solution with EnviroGear that is going to perform very well in this harsh environment."

- Engineering Staff Member, Unilever North America





PSG 22069 Van Buren Street Grand Terrace, CA 92313-5607 USA P: +1 (909) 422-1731 F: +1 (909) 783-3440 envirogearpump.com